HIGH RISK **Health & Safety Affinity Water** MEDIUM RISK **First Alert** LOW RISK Fatality RIDDOR Specified Injury RIDDOR >7-day injury **RIDDOR Dangerous** X Lost Time Injury (<7day) Classification: High Potential Event Occurrence Road Traffic Collision Service Strike Incident Date / Time: 2nd December 2024, 05:45 Location: The Grove Depot **Customer Operations Supplier Business Area:** Performance Mobile Stores Person Occupation: **Details of Injury /** Upper leg area badly bruised Damage: Paul Element Responsible Manager: **Contractor Name:** N/A 70968 **EcoOnline ID:** On arriving on site, the IP pulled his vehicle up in front of the first set of gates. The access road at this point is on a slight downward slope. He exited the vehicle and proceeded to unlock and open the gates, starting with the left hand gate on the offside of the vehicle. **Brief Description:** As he was doing this, he noticed the vehicle starting to move down the slope. He ran across the front of the vehicle to attempt to enter the drivers door and apply the brake but in doing so was trapped by the vehicle against the right hand gate and fence. He remained trapped for approximately 19 minutes until his calls for help were heard by **Immediate Actions** a local resident. At 06.05 The local resident (also a doctor) reversed the vehicle and Taken: assisted the IP initially before calling the emergency services. The IP was taken to hospital by the ambulance. Full investigation to be completed, including checks to vehicle by a garage.

Local Incident Review to be held.

Learning to be shared to all Affinity Water and partners

Template Ref: AW0262

Template Issue: 1.3

Issue Date: 19/05/2022

Review date: 19/05/2025

Next Steps: