

	<h1 style="text-align: center; color: white;">Health & Safety First Alert</h1>				<input checked="" type="checkbox"/> HIGH RISK <input type="checkbox"/> MEDIUM RISK <input type="checkbox"/> LOW RISK
	Classification:	Fatality Lost Time Injury (<7day) Road Traffic Collision	RIDDOR Specified Injury RIDDOR Dangerous Occurrence Service Strike	RIDDOR >7-day injury High Potential Event Near Miss	 X
Incident Date / Time:	09/05/2025 11.30am				
Location:	Preston Reservoir				
Business Area:	Capital Delivery				
Occupation:					
Details of Injury / Damage:	No Injuries Sustained / damage to telehandler				
Responsible Manager:	Phil Algawi , AW Senior Project Manager				
Contractor Name:	OCU Group				
EcoOnline ID:	76791				
Brief Description:	On the 9th May 2025, at approximately 11:30am, an OCU telehandler drove up the ramp access to off-load deck drain material to the top of the roof of the reservoir. After offloading the deck drain material at the top of the ramp access, the telehandler operator proceeded to reverse back down the ramp. When the telehandler reached the foot end of the ramp, he unfortunately turned the steering wheel, thinking he was in a safe position to turn, it was at this point, the telehandler tipped onto its left side.				
Immediate Actions Taken:	<ul style="list-style-type: none"> Area was cordoned off and area made safe. Operator recovered from the cab of the telehandler. The operator was examined by the onsite First Aider, for possible injuries. All plant movements on and near the ramp escarpment was immediately stopped. Spill kits deployed to prevent any further ground contamination. 				
Next Steps:	<ul style="list-style-type: none"> Full investigation to be completed. Local Incident Review to be held. Learning to be shared to all Affinity Water and partners. 				

