# RIDDOR incident: Fractured fibula (slip injury)

To All staff – Wholesale Water, Wholesale Wastewater, Engineering and Construction Date August 2021

From HSSW Team Recommended circulation All operational staff and supply partners

#### Incident

While accessing a wash-water hose, an employee sustained a fractured fibula (leg bone) as a result of slipping on wet and uneven ground. Over a third of all major injuries reported each year are caused as a result of a slip or trip (the single most common cause of injuries at work). Employees are reminded to always use designated pathways and to ensure that all work equipment is stored safely after use.

## **Images**





#### Immediate actions

- Use access paths where provided. Do not walk onto any wet grass especially on inclined areas. Conduct personal risk assessments routinely.
- Ensure hose pipes are always left accessible, but stored safely to prevent trip hazards.
- Report any access and egress issues particularly where footpaths are not sufficient or where footpaths are in poor condition. Don't take short cuts.
- Report all hazards and near misses on 0800 027 0886

### Additional sources of information

Safety instruction 555: Personal risk assessment

Safety instruction 602: Good housekeeping

HSE guidance STF: https://www.hse.gov.uk/pubns/indg225.pdf

Contact your HSSW Advisor if you have any concerns regarding access

or egress

# 08/21 Southern Water Safety Alert

See it, sort it, report it Report all hazards and near misses via 0800 027 0886



Please ensure that these bulletins are cascaded through your part of the organisation's structure and displayed at manned operational sites