

AffinityWater	<h1 style="margin: 0;">Health & Safety</h1> <h2 style="margin: 0;">First Alert</h2>			<input checked="" type="checkbox"/> HIGH RISK <input type="checkbox"/> MEDIUM RISK <input type="checkbox"/> LOW RISK
Classification:	Fatality	RIDDOR Specified Injury	RIDDOR >7-day injury	
	Lost Time Injury (<7day)	RIDDOR Dangerous Occurrence	High Potential Event X	
	Road Traffic Collision	Service Strike	Near Miss	
Incident Date / Time:	28/05/2026 10:50			
Location:	Bank of settling res by pre-ozone, Chertsey WTW			
Business Area:	Estates & Facilities			
Occupation:	Contractor Operative			
Details of Injury / Damage:	Damage to lawnmower and to grass embankment			
Responsible Manager:	John Merrill			
Contractor Name:	Pro Landscapes			
EcoOnline ID:	89593			
Brief Description:	<p>Pro Landscapes contractor was mowing the grass on the settling res bank. They somehow lost control of the mower which caught fire, with the mower rolling down the bank.</p>			
Immediate Actions Taken:	<p>The area was evacuated, The fire service were called, and the pre-ozone treatment was turned off due to concerns around the flammability of gas.</p> <p>The fire service attended and extinguished the fire.</p>			
Next Steps:	<ul style="list-style-type: none"> Completion of the investigation Incident to be reviewed at a Local Incident Review Learning Bulletin to be shared if there are key messages that need to be communicated 			

