


- On Monday 12 May, a team of 4 operatives were undertaking a pipe cleaning activity.
- During this process, the pipe cleaning device (Pipe 'PIG') left the confines of the pipe whilst still under power.
- At this point, the left hand of a general operative came into contact with the rotating arms of the pipe 'PIG'.
- The IP sustained a significant hand injury and was taken to hospital for surgery.
- All pipe cleaning operations using the pipe 'PIG' have temporarily ceased across SPA.
- Principal contractor and SPA SHEA advisors have been deployed to site to gather information and begin the investigation process.

For Anglian Water employees, partners and contractors

They are issued to raise awareness of incidents that occur and to highlight the safe work practices required to avoid them being repeated.



- Pipe cleaning activities using the pipe 'PIG' are not to recommence until a full review of the operation has been undertaken and additional controls have been implemented to prevent contact with moving machinery that is not guarded.
- A review of RAMS and Permit documentation has been implemented.
- Please review all site activities that have the potential for contact with moving machinery to ensure suitable guarding / exclusion areas are in place.

Injuries can be prevented, have you stopped to think about your safety?